## Uchiyama MFG America LLC

494 Arrington Bridge Rd, Goldsboro NC, 27530



## COVID-19 Response

- Customers still require some support for parts
  - GM, Ford, Chrysler, Toyota, Honda, etc
- Reduced production by near 75%
- Machine shutdowns -
- Personnel schedules 3/2, staggered shifts, RIFs

## Post Event Power Restoration

- Surge Protectors at all Switchgears and Panels
  - Open switchgears, if possible
- Open disconnects at machines
- Start process equipment first
  - Boiler, Cooling Towers, Air Compressors (Inteliflow)
  - Have a contingency plan
- Evaluate high demand energy sources
  - Inject Mold Machines
  - Start these singularly

## Uchiyama MFG America LLC

494 Arrington Bridge Rd, Goldsboro NC, 27530

